

Bubble Visor

Cleaning Instructions

General cleaning of the bubble visor should be done with a clean, dry cloth or paper towel, by simply wiping away dust and dirt. However, when more substantial cleaning is necessary, running water over the visor may be necessary. In this case, clean the visor with running water from the tap, but **DO NOT WIPE THE VISOR WITH ANYTHING WET**. This will smear the anti-fog coating causing the visor to be cloudy and unusable. If the visor is wet, it will be allowed to air-dry without wiping. Once the visor is dry, a clean and dry cloth or paper towel can be used to remove any remaining dirt.